




08 - 2010
Part No. 195413-9
Bolted Blade Clamp Set
 (For Model: JR3060T, JR3070CT)



| Item No. | Part No. | Description | Qty | Unit |
|----------|-----------|--|-----|------|
| 1 | 140695-8 | SLIDER N COMPLETE (N/A as individual part) | 1 | PC. |
| 2 | 232165-2 | LEAF SPRING | 1 | PC. |
| 3 | 266090-5 | HEX. SOCKET HEAD BOLT M5X15 | 1 | PC. |
| 4-1 | 266202-0 | SET SCREW M8X10 | 1 | PC. |
| 4-2 | 266202-0A | SET SCREW M8X10 | 1 | PC. |
| 5 | 313075-3 | BLADE CLAMP | 1 | PC. |
| 6 | 410048-8 | WRENCH HOLDER 3.4 | 1 | PC. |
| 7 | 783202-0 | HEX. WRENCH 4 | 1 | PC. |
| 8 | 831203-3 | POLY BAG 70X110 (N/A as individual part) | 1 | PC. |
| 9 | 831204-1 | POLY BAG 145X220 (N/A as individual part) | 1 | PC. |

- Service Note -

- 1) Remove Item No. 3-12, 24, 64-66 from the tool in order to assemble 195413-9 to the tool.
- 2) When removing Item No.24 (Slider complete), Item No. 29 and 42 (P.H.Screw) need to be removed as well. The screws (Item No.29 & 42) are with adhesive. They should be renewed or re-used with adhesive when assembling.