



| Item No. | Type | Sub | Part No. | Description | Qty | Unit |
|--------------------|------|------|------------|--|-----|------|
| 001 | | | GM00001332 | SCREW 3 X 8 PB | 4 | PC. |
| 002 | | | GM00002360 | LENS COVER ASSY | 1 | PC. |
| 003 | | | GM00002204 | LENS | 1 | PC. |
| 004 | | | GM00002205 | LENS O-RING | 1 | PC. |
| 005 | | | GM00002206 | REFLECTION CUP COVER | 1 | PC. |
| 006 | | | GM00002207 | LED O-RING | 4 | PC. |
| 007 | | | GM00002208 | O-RING | 1 | PC. |
| 008 | | | GM00002209 | REFLECTION CUP | 1 | PC. |
| 009 | | | GM00001322 | SCREW 2.6X8 PB | 4 | PC. |
| 010 | | | GM00002211 | O-RING | 1 | PC. |
| 011 | | | GM00002362 | LED & HEAT SINK ASS LED | 1 | PC. |
| 012 | | | GM00002218 | RIGHT LATCH PLATE | 1 | PC. |
| 013 | | | GM00002217 | LEFT LATCH PLATE | 1 | PC. |
| 014 | | | GM00002219 | SCREW 2.6X7 KB | 4 | PC. |
| 015 | | | GM00002219 | SCREW 2.6X7 KB | 4 | PC. |
| 016 | | | GM00002363 | LIGHT HEAD CASE ASSY | 1 | PC. |
| 017 | | | GM00002212 | SCREW 3X8 PM | 2 | PC. |
| 018 | | | GM00001012 | SCREW 3X12 PB BLACK ZN | 5 | PC. |
| 019 | | | GM00002364 | LEFT & RIGHT HOUSING ASSY | 1 | PC. |
| | | INC. | | Item No. 34 | | |
| 020 | | | GM00002225 | LATCH PIN | 1 | PC. |
| 021 | | | GM00002224 | COMPRESSION SPRING | 1 | PC. |
| 022 | | | GM00002251 | SPRING CLIP 2X10X25 | 1 | PC. |
| 023 | | | GM00002371 | RIGHT HOUSING COVER | 1 | PC. |
| 024 | | | GM00002226 | SHAFT O-RING | 2 | PC. |
| 025 | | | GM00002219 | SCREW 2.6X7 KB | 4 | PC. |
| 026 | | | GM00002219 | SCREW 2.6X7 KB | 4 | PC. |
| 027 | | | GM00002226 | SHAFT O-RING | 2 | PC. |
| 028 | | | GM00002225 | LATCH PIN | 1 | PC. |
| 029 | | | GM00002224 | COMPRESSION SPRING | 1 | PC. |
| 030 | | | GM00002251 | SPRING CLIP 2X10X25 | 1 | PC. |
| 031 | | | GM00002365 | LEFT HOUSING COVER ASSY | 1 | PC. |
| 032 | | | GM00002250 | SCREW 2.0X5 KB | 1 | PC. |
| 033 | | | GM00002222 | LINE PRESSING BLOCK | 1 | PC. |
| 034 | | | GM00002364 | LEFT & RIGHT HOUSING ASSY | 1 | PC. |
| | | INC. | | Item No. 19 | | |
| 035 | | | GM00002249 | SWITCH SPRING | 1 | PC. |
| 036 | | | GM00002230 | WHITE SWITCH ASSY | 1 | PC. |
| 037 | | | GM00001322 | SCREW 2.6X8 PB | 2 | PC. |
| 038 | | | GM00002367 | MAIN PCBA(SMD+ DIP) | 1 | PC. |
| 039 | | | GM00002366 | SILICONE & HEAT SINK(IC) | 1 | PC. |
| 040 | | | GM00002368 | DIMMER SWITCH RUBBER | 1 | PC. |
| 041 | | | GM00002369 | SWITCH SUPPORT | 1 | PC. |
| 042 | | | GM00002370 | ML007G FUSE PCB SP (ROHS) | 1 | PC. |
| 043 | | | GM00002374 | BATTERY HOLDER ASSY | 1 | PC. |
| 044 | | | GM00002284 | RING | 1 | PC. |
| 045 | | | GM00002231 | STRAP HOOK | 1 | PC. |
| 046 | | | GM00002372 | HANGING HOOKS | 1 | PC. |
| ACCESSORIES | | | | - Visit www.makita.ca for more accessories information - | | |
| A01 | | | GM00002373 | HAND STRAP WITH METAL STRAP HO | 1 | PC. |
| A02 | | | ----- | 40V MAX LI-ION BATTERY | 1 | PC. |
| A03 | | | DC40RA | FAST CHARGER DC40RA | 1 | PC. |